

## APPENDIX V: BUILT SITE

---

### EXTERIOR SURVEY REPORT

A site survey of the Capitol grounds was performed in March and June of 2000 to determine the condition of site features such as sidewalks, curb and gutter, stairways, parking lots, and utilities. The purpose of the site survey was to identify elements that are in satisfactory condition and elements that may be in need of repair or replacement to increase safety and improve function. The existing site elements were then photographed and logged. The photographs were entered into an Access database template and labeled with the appropriate date, category, location and condition. Descriptions of the condition codes are listed in the table below. If an item was in good condition, the “satisfactory” box was checked. If damaged, the “damaged” box was checked and then the appropriate code and description detailing the type of damage and necessary action appear below. A majority of the items in the Exterior Survey Report were in satisfactory condition, with the exception of those mentioned in the Built Site Features section of this Report. The figure on the following page shows a map with the location of each photo as numbered in the “ID” field at the top of each data sheet.

<b><u>Code</u></b>	<b><u>Description</u></b>
BR	Broken , severely cracked or chipped, needs repair or replacement
C	General Cleaning Needed
CK	Caulking missing, damaged or non-matching, needs replacement
CO	Cracked, spalled, damaged concrete, needs repair or replacement
EX	Exfoliated or spalled surface; needs repair and correction of water problem
FL	Flashing pulled away or damaged, needs repair
GL	Glass cracked, broken or non-matching, needs replacement
INT	Intrusive, non-original, non-essential element, needs removal and patching
J	Mortar joint with missing or loose mortar, needs repair
M	Missing element, needs replacement with matching piece
MT	Metal damage, needs repair or replacement
NO	Non-original, incompatible but essential elements, consider matching replacement
O	Other (describe)
P	Paint missing or damaged, needs repair
PAT	Poor quality, non-matching patch, needs replacement with matching patch
PL	Plaster damage or no-original, non-matching work, repair or replace
R	Roof cracking or damage, needs repair or replacement
ST	Significant Staining, needs cleaning; may indicate rusted connector
W	Deteriorated or damaged wood, needs repair or replacement